MEMORANDUM

TO

: AVP TPE

DATE: 18 August 1970

FROM

: BMSGN

REF. No. BMSGN/70/252

SUBJECT: July Monthly Report -

Saigon Base Monthly Report for July 1970 is forwarded in three copies for your file.

E.J. Theisen

FORM 5270400

SAIGON BASE MONTHLY REPORT JULY 1970

- I. GENERAL
- 1. Total block time for July was 5295 hours as compared to 6398 for July 1969, and 5588 home for june 1970.
- 2. VTB N3728G was positioned to Udorn on 1 August 1970, and on 28 July 1970 VTB N9838Z was removed from temporary storage and placed on the 7001 contract.
- 3. Vietnamese students supported by other Allied Representatives have held a demonstration on 11 July 1970 declaring that they want to obtain Peace, Independence and Unification for Vietnam without American and Allied troops' help and support. Nixon is only a war monger, all American must withdraw from Vietnam.

On July 20th, at 1530, VC launched two rockets: one hit the yard of the Independence Palace, another landed in downtown Saigon area. Also on 25 July, a plastic bomb was detonated behind the 3rd Field Hospital, a few miles from the airport, causing minor damage.

Cn July 22nd, an Air Vietnam domestic flight (Pleiku-Saigon) was hijacked by an American GI Capt F.L. Derieux (former AAM pilot) and two other foreans crew members were involved. Unofficial sources reported that attempted to escape to Hongkong due to the previous crime he has had committed during his tour in Vietnam. The diagraft landed Safety in Saigen and the hijacker was apprehinder.

On July 27th, the Vietnamese students and disabled veterans attacked the Indian Consulate at Saigon protesting against the official welcoming of Madame Nguyen Thi BINH who is the Minister of Foreign Affairs of the Liberation Front (VC).

4. Local management has been approached both at DAD and SGN by US Air Force Representatives concerning master planning which, if effective, would relocate the AAM DAD Operations across the runways to the military side of the field. This matter has been turned over to the customers to take up with proper authorities.

AR 2438 - Completion of Concrete Pavement and Drainage Ditch, DAD Complete.

AR 2437 - Improvement on Passenger Lounge, DAD
This project is out for bid. Expect it will take 30 days to complete after starting construction.

AR 2422 - Renovation of the Operations Building, SGN
This project moving along quite rapidly, should be complete by 30
September 1970.

AR 8320 - Danang Hostel & SZ Residence Renovation
This project is complete. Pictures will be forwarded in the near
future. To give you a feeling for the vast improvement which has
been effective.

AR 2449 - Saigon Terminal Parking Apron
Only one bid from A&M Enterprises was received on this project which
fell within the limit of the approved AR & Form F. Customer John
Williams has approved. Letter being forwarded to PRES and SLC for
approval to sub-contract. Construction time required is about 45
days.

- 5. The Ministry of Foreign Affairs of the Republic of Vietnam has sent instructions to all Vietnamese Embassies/Consulates abroad that starting 14 August 1970 the new regulations will apply ---all nationals including American must obtain entry visa before entering the Republic of Vietnam. The seven-day stay without visa in SVN is no longer granted to Americans or any other foreign nationals.
- II. CUSTOMER RELATIONS remain excellent as ever.

III. FLYING

- 1. Facilities inspections were made at Can Tho and Da Nang primarily for the purpose of getting a check made of the water used for showers, but at present we have not received any specific results. MFD's visit to Da Nang was cut short with the arrival of VPFO continuation of MFD's visit will be made in August.
- 2. The grievance hearing for P.A. Broussard and G.V. Parker was held, and due to the lack of complete evidence, including "failure-to-appear" on the part of the customer who initiated the original complaint, it was recommended that both pilots be reinstated. This was upheld by Taipei and they were returned to duty, retroactive to the date they were withhold from service.

Renovation and construction was started on the FD/OPs building in Saigon.

VPFO and MVPFO made separate visits to Saigon.

Our safety record went "down the drain" with the gear-up landing of VTB N7770B at Bac Lieu (V58).

IV. MEDICAL
Number of sick call: 120
Accidents: 50
Hospitalized sick call: lone
Unhospitalized accident: 50
Outcall: 1
Physical examination: 22
Sick leaves: 3392

V. PERSONNEL

- 1. Personnel Department activities were routine. PM was on Annual Leave from 11 July-8 August 1970.
- 2. Our appeal through the US Embassy for the reconsideration of the work permits were successful. We have just obtained the reconsideration for the work permits of 10 TCN from the RVN Ministry of Labor.

The piaster is being traded in the open market at approximately VN\$380 to US\$1.

3. Personn	el Strength						m	
Classif. Permanent	GED FLT	GRD FLT	GRD	FLT	GAD	FLT	Total GRD FLT	•
	34 132	117 13	133	3	8	3	292 151	
	GRD FL	r GRĎ		GRID	GR		Total GRD FLT	
	485# 14	*** 2		2		1*	490 14	

Temporary:

Pre-processed: GRD 75

(*)

Ground Personnel: 790 Flight Personnel: 165 (**) (#)

Total : 955

Danang Sub-Base

				Total
Classif. Permanent GRD	GRD	GKD	GED	GRD
3	13	17	69	102
Pre-processed:	GRD	1		

Ground Personnel: 103

		Nha	Trang Sub-Bas	3 e	Total
Classif. Permanent	CRU	GRD 8	GRD 22	GRD 56	GaD 90
Pre-proces	ssed.			2	

Ground Personnel: 92

Can Tho Sub-Base

Classif. Permanent	GRD	GRD	GRD	Total GRD	
•	. 1	10	3	14	

VL. FISCAL

1. A group of officials from the Philipines visited to discuss banking in the Philipines. They were treated with every courtesy

2. We were queried by Taipei regarding non-logging of project time. Seems that the customer, after signing the log sheets for 10 months discovered that we were no longer logging project time. Our pilots will start logging project time in August.

HOTEL/HOSTEL OCCUPANCY

		Beds Available	Beds Utilized
a.	Danang	588	332
b.	Nha Trang	513	407

c. Saigon - Not even a single certificate of "Non-Availability of company furnished accommodations was issued during this month.

VII. OPERATIONS

- 1. Plight Time Report (See attachment A)
- 2. Ground Fire Incidents Report (See attachment B)
- Ground Transportation

Aggregate microbuses mileage: 24852 km approx. 15532 miles

Total microbuses downtime: 256 hrs 48' Total microbuses pax carried: 3235 pax

Isuzu bus mileage: 6130 km approx. 3831 miles

Total Isuzu bus downtime: 41 hrs 32' Isuzu bus pax carried: 10288 pax

Supply vehicle mileage: 3055 km approx. 1909 miles

Supply vehicles downtime: 21 hrs. 48'

VIII. TRAFFIC/AAM

	June	July
Passengers departure SGN (all contracts)	5,432	5,771
Passengers arrival SGN (all contracts)	6,231	6,486
Outbound cargo SGN 11	,6,640	65,891
Inbound cargo SGN	70,700	68,553

Cargo (including AF Caribou A/C)

	June	July
Outbound (1bs) SGN	800,054	706,114
Inbound (1bs) SGN	392,621	231,436

IX. TECHNICAL SERVICES

1. There is little to report in Technical Services - SVN, activities for July versus that of June. In the aircraft activities, flying hours utilized were approximately the same. The workload due to delays, recoveries and premature engine removals was down slightly.

Initiation of the new Skilled Labor Cost Accounting System was off on Schedule, 1 July. Preparatory training was carried out, but such a program requires strong and constant supervisory follow-up.

General Maintenance activities at SGN includes the start of renovation of the Flight and Operations department building; installation of the 160 kW standby generator, water faucets for aircraft washing to reduce towing and accident potential, area beautification and general house-keeping. At Danang, the terminal/hangar area concreting is approximately 90% complete and the hostel is complete except for touch-up.

- 2. Aircraft Maintenance Fixed Wing. There were several incidents during the month involving aircraft accidents. Two aircraft received minor damage due to hostile fire action, one aircraft had propeller damage due to FOD, another aircraft lost a cargo door in flight and one aircraft was involved in a major accident by landing on the runway with gear-up position.
- 3. Rotary Wing This month has been a little slow; two number two service at DAD, five number two, one number 3A and one number 3B, and one number 4A service at Saigon.
- 4. Shops The overall shops workload remained steady with a certain amount of overtime required for N198X number 4 service.
- 5. General Maintenance Building and Grounds Maintenance Water pipe has been run through existing culverts under the taxiway from the RMD building to the South Mamp. Water pipe has also been installed along the north side of the Northeast Ramp.
- 6. Electronics PABX and Intercom Systems We have one PTT trunk line that can be used and another line (on emergency basis only) that can be used to call Saigon telephones thru the PABX operator.

CMD has recently finished the installation of the Paging System, initiated a year ago. Ten speakers are distributed to cover all existing AAN Hamps, inside hangar, sheet-metal shop and Cafeteria. One dynamic microphone and two 100-watt Philips amplifiers are used to operate these speakers.

7. Technical Training - Courses completed: Quality control Inspector Training; Carrett TPR-331; Supply Course; Flight Mechanic's Course.

Courses in progress: Line Service Mechanics Course; Welding Course.

8. Supply - Supply activities remained the same as last month. The 2nd Supply Training Course for newly employed storekeepers was conducted this month. The students gained considerable basic knowledge of the functions of the supply business.

The Procurement Section of RSD SGN experienced a slightly smaller amount of transactions than last month. A total of 171 line items of commodities were purchased from local market this month.

Total value of commodities purchased from Saigon/Cholon market amounted to VN\$ 765,857.00.

Since Naval Support Activity (NSA) in Danang has been deactivated, 60% of the general supplies have been purchased from HAG.

E. J. Theisen

SAIGON BASE PLIGHT THE REPORT

- JULY 1970 -

1.	Contract 7001 -	Rem		Boo-Ro	Constitute
	NC No.	Block Time	Plight time	Block Time	Flight Time
	N67984	115+03	99+22	18+40	16+38
	167985	134+67	117+33		
	B928	83+28	66+19		
	B910	87+50	77+29	12+38	10+15
	B91 2	89+21	70+47		
	6147	59+58	49+51		
	5559	76+46	63+32		
	5994	172+00	141+14		
	3629	126+35	106+16	1+05	0+39
	#539Y	219+55	98+13	27+18	23+52
	H54AY	149+35	125+08	25+55	23+45
	B851.	142+58	114+00	23+49	21+46
	1951.8 Z	72+32	60+37		
	n6154 U	74+55	65+12	3+57	3+11
	1199562	90106	76+35	16+16	13+53
	177708	110102	95+16	1+24	0+57
	1495772			3+17	2+27
	N3674G	19+35	16+23	•	. •
	N91295	76+45	65+35	1+05	0+55
	N963.82	0148	0+21	1+05	0+50
	13728G	61 +39	72+07	5+43	3+54
	¥76950	115+22	96+10	0+22	0+17
	MISOR	137+42	123+11	0+33	0+18
	N2851.	95+38	85129		
	N391 R	9+10	9+16		
	R394R	51+34	45+21	E4+0	0+18
	119444	44+38	39+36	-	
	N198X	80+38	69+13	1+49	1+13
	K153 L	147+10	127+04	0+34	0107
	N12450	15+39	12443	046	0+33
	w?aan	61+03	51407	3+37	3+07
	K152L	91+41	77+34	13+40	11+46
	MISAI.	126+49	105+29		-
	r185X	111+53	99+25		
	N192X	122+37	110+12	0+57	0+37
	N194X	109+15	90+59	6+54	5+33
	N393R	30+13	26+40	4+56	4126
	H13G3X	108+04	108+04	16+12	16+12
	M1304X	111+53	111+53		
	M305X	109+09	109+09	4+15	4+25
	101306X	109+01	109+01	2+15	2+15
	x03071	128+36	128+36	13+00	13+00
	¥8514F	169+13	169+13	2+50	2+50
	N8535F	11+09	11+09	4+38	4+38
	Sub-total	3982+45	3498+24	219+53	194+27

^		- 2		
2,	Contract 7002 -			
	B651	1+29	1+18	
	N9518Z	4+46	3+33	
	M6154U	48+23	42+39	
	19956Z	13+38	11+29	
	¥7770B	8+20	7+10	
	¥36740	77+51	66+18	
	191295	12+50	10+27	
	198382	2+22	1+59	
	13728G	11+25	9+20	
	117695C	2+55	2+14	
	1285L	52+12	47+37	
	1391R	75+54	65+20	
	1394B	104+58	97+47	
	N9444	14+46	13+37	
	N198X	60101	50+12	
	10.53 L	8137	7+34 62+27	
	N12450 N748h	69105 6145		
	M152L	9143 8+25	4+59 7+40	
	MISSI	6424	5+10	
	H185K	25+57	23+36	
	1192X	17+00	14+52	
	XI.9AX	9+53	8+15	
	1393R	72+12	61+39	
	N1303X	4137	4+37	
	H1304X	18+11	18+11	
	H1305X	24+03	24+03	
	H1306X	14+15	14+15	
	10307X	8+02	8+02	
	¥8514P	12+14	12+14	
	Ne53 51*	74+12	74+12	
	Sub-total.	871+42	782+46	
3.	Contract 7003 -	871+42		
3.	Contract 7003 - #67985	871+42 6+08	5+32	
3.	Contract 7003 - M67985 B928	871+42 6+08 27+28	5+32 22+13	
3.	Contract 7003 - #67985 #928 #910	871+42 6+08 27+28 40+46	5+32 22+13 34+19	
3.	Contract 7003 - #67985 #928 #910 #912	871+42 6+08 27+28 40+46 54+51	5+32 22+13 34+149 13+06	
3.	Contract 7003 - #67985 B928 B910 8912 6147	871+42 6+08 27+28 40+46 54+51 20+11	5+32 22+13 34+149 13+06 13+11	
3.	Contract 7003 - M67985 B928 B910 8912 6147 5559	871+42 6+08 27+28 40+46 54+51 20+11 10+31	5+32 22+13 34+149 43+06 13+11 6+15	
3.	Contract 7003 - #67985 #928 #910 #912 6147 5559 #829	871+42 6+08 27+28 40+46 54+51 20+11 10+31 8+11	5+32 22+13 34+19 13+11 6+15 5+14	
3.	Contract 7003 - #67985 #928 #510 #912 6147 5559 #829 #539X	871+42 6+08 27+28 40+46 54+51 20+11 10+31 8+11 7+28	5+32 22+13 34+149 13+11 6+15 5+14 5+59	
3.	Contract 7003 #67985 #928 #510 #512 6147 5559 #829 #539X	871+42 6+68 27+28 40+46 54+51 20+11 10+31 8+11 7+28 11+12	5+32 22+13 34+149 13+06 13+11 6+15 5+14 5+59 9+30	
3.	Contract 7003 R67985 B928 B910 B912 6147 5559 B829 R539Y R544Y B851	871+42 6+08 27+28 40+46 54+51 20+11 10+31 8+11 7+28 11+12 4+43	5+32 22+13 34+19 13+06 13+11 6+15 5+14 5+59 9+30 3+35	
3.	Gentract 7003 - M67985 B928 B910 8912 6147 5559 B829 M539X M544X B851 M6154U	871+42 6+08 27+28 40+46 54+51 20+11 10+31 8+11 7+28 11+12 4+43 4+20	5+32 22+13 34+149 13+06 13+11 6+15 5+14 5+39 9+30 3+35 2+51	
3.	Contract 7003 - M67985 B928 B910 8912 6147 5559 B829 M539X M544X B851 M6154U M3728G	871+42 6+08 27+28 40+46 54+51 20+11 10+31 8+11 7+28 11+12 4+43 4+20 2+43	5+32 22+13 34+149 13+11 6+15 5+14 5+59 9+30 3+35 2+51 1+57	
3.	Contract 7003 - M67985 B928 B910 8912 6147 5559 B829 M539X M544X B851 M6154U M37280 M76950	871+42 6+08 27+28 40+46 54+51 20+11 10+31 8+11 7+28 11+12 4+43 4+20 2+43 1+41	5+32 22+43 34+49 43+06 13+11 6+45 5+44 5+59 9+30 3+35 2+51 1+57 1+21	
3.	Contract 7003 - M67985 B928 B910 8912 6147 5559 B829 M539X M544X B851 M6154U M3728G	871+42 6+08 27+28 40+46 54+51 20+11 10+31 8+11 7+28 11+12 4+43 4+20 2+43	5+32 22+13 34+149 13+11 6+15 5+14 5+59 9+30 3+35 2+51 1+57	
3.	Contract 7003 - M67985 B928 B510 8912 6147 5559 B829 M539X M544Y B851 M6154U M3728G M7695C H2851	871+42 6+08 27+28 40+46 54+51 20+11 10+31 8+11 7+28 11+12 4+43 4+20 2+43 1+41 2+13	5+32 22+13 34+149 13+111 6+15 5+14 5+39 9+30 3+35 2+51 1+57 1+21 1+56	
3.	Contract 7003 - #67985 #928 #910 #912 6147 5559 #829 #539X #544X #851 #6154U #3728G #7695C #2851 #1531	871+42 6+68 27+28 40+46 54+51 20+11 10+31 8+11 7+28 11+12 4+43 4+20 2+43 1+41 2+13 1+02	5+32 22+43 34+49 43+06 13+11 6+45 5+44 5+59 9+30 3+35 2+51 1+57 1+21 1+56 0+48	
3.	Gentract 7003 - N67985 B928 B910 8912 6147 5559 B829 M539X N544X B851 M6154U M3728G M7695C M2851 H1531 M748M M1521 H1841	871+42 6+08 27+28 40+46 54+51 20+11 10+31 8+11 7+28 11+12 4+43 4+20 2+43 1+41 2+13 1+02 2+26 2+16 8+28	5+32 22+13 34+149 13+11 6+15 5+14 5+59 9+30 3+35 2+51 1+56 0+18 2+00 1+10 6+03	
3.	Gentract 7003 - N67985 B928 B910 8912 6147 5559 B829 N539X N544X B851 N6154U N3728G N7695C N2851 H1531 N74MN N1521	871+42 6+08 27+28 40+46 54+51 20+11 10+31 8+11 7+28 11+12 4+43 4+20 2+43 1+41 2+13 1+02 2+26 2+16	5+32 22+13 34+19 13+06 13+11 6+15 5+44 5+39 9+30 3+35 2+51 1+56 0+18 2+00 1+10	

		N393R N1304X N1307X	0+40 24+54 15+06	0+00 24+54 15+06	
		Sub-total	262+20	213+04	
4.	Contract	0030 -			
		N9577Z	49+46	1241	
		¥152L	4+35	3+52	
		Sub-total	54+21	46+33	
5.	Contract	0069 -			
		16154U	1+39	1+28	
		136740	5+19	4+46	
		19664C	106+36	91+49	
		N7695C	10+00	8+45	
		N12450	1+28	1+22	
		1393R	2+04	1+50	
		Sub-total	127+06	130+00	
		TOTAL REVE	NUE BLOCK T	IMB	5298+14
		TOTAL REVE	MUE PLICHT	TIME	4650+47
		TOTAL NON-	SEASTANTE BYO	CE TIME	219+53
		TOTAL NON-	REVERUE FLI	CHT TIME	194+27
		GRAND TOTA	L BLOCK TIP	8	5518+07
		GRAND TOTA	l floht ti	3 5	4245+14

Flight Time by Type of Aircraft.

	Reverus			Yenre
Type of A/C	Block Time	Flight Time	Block Time	Flight Time
C-46	639+42	537+40	31+18	26+53
Bailed C-47	339+26 134+46	274+33 112+00	1+05	0+39
DEC-4	437+20	357443	77402 33409	69+23 26+24
VTB PC-6	1006+18 1798+03	8 60+03 1566+09	34109	27+58
204-8	942+39	942+39	13+10	43+10
TOTAL	5298+14	4650+47	219+53	194+27

Original Signed By L. Co. PARRISH SON/SON

oe i Beyson NFD/SGN Th/Sch